





- NOTES:
- BREAK ALL SHARP EDGES
 - FITMENT WITH MATING PART/GAGE SHOULD BE INSPECTED PRIOR TO BREAKING DOWN SETUP

THIS PRINT IS FOR EDUCATIONAL PURPOSES ONLY.

 POWERING AMERICA'S WORKFORCE		SLOT ASSEMBLY 1.1	
TOLERANCE		DRAWN BY: WESLEY CIFERS	
X.X ± .010		8/15/2023	
X.XX ± .005			
X.XXX ± .003			
ANGLES ± 1°			
MATERIAL: 6061 AL		DWG NO: 00070	
SCALE: 1:1			
A		SHEET: 1/1	
		REV: 1	